



ITEM	PART NO	DESCRIPTION	Q'TY	TYPE	REMARK
1	340673410001	COVER ASSY;8640G	1	ASSEMBLY	
2	340673400004	HOUSING ASSY;8640S	1	ASSEMBLY	
3	340673400012	SHIELDING ASSY;TOP,8640S	1	ASSEMBLY	
4	411673430001	PWA;PWA-8640D,MOTHER BD	1	ASSEMBLY	
5	441999900069	BATT ASSY OPTION;LI,12-CELL,8640G/P	1	ASSEMBLY	
6	523467341001	HDD ASSY;DK23DA-40,HITACHI,8640G	1	ASSEMBLY	
7	523467340007	DVD COMBO ASSY;MATSUSHITA,8640	1	ASSEMBLY	
8	340673400010	THERMAL ASSY;8640S	1	ASSEMBLY	
9	340673400003	COVER ASSY;KB,8640S	1	ASSEMBLY	
10	531020237483	KBD;88,GR,K010718VI,8640,DARK BLUE	1	PART	
11	340673400001	PLATE ASSY;K/B,8640S	1	ASSEMBLY	
12	344673400009	COVER;SPEAKER,8640S	1	PART	
13	340673400006	SPEAKER ASSY;BOX,8640S	1	ASSEMBLY	
14	442110500012	TOUCH PAD MODULE;TM41PUG311-2	1	PART	
15	340673400013	BRACKET ASSY;T/P,8640S	1	ASSEMBLY	
16	342673410001	BRACKET;CARD-READER,8640G	1	PART	
17	421673410003	FPC ASSY;CARD-READER,8640G	1	ASSEMBLY	
18	411673400005	PWA;PWA-8640,ESB/LED BD	1	ASSEMBLY	
19	340673400008	COVER ASSY;MINI PCI,8640S	1	ASSEMBLY	
20	344673400025	COVER;HINGE R,8640S	1	PART	
21	344673400016	COVER;HINGE L,8640S	1	PART	
22	421673400003	MICROPHONE ASSY;8640S	1	ASSEMBLY	
23	377244010002	STANDOFF;#4-40DP3.5H5L5.5,NIW	4	PART	
24	370102610805	SPC-SCREW;M2.6L8,K-HD,NIW/NLK	15	PART	
25	370102010405	SPC-SCREW;M2L4,NIW,K-HD(+),NYLOK	19	PART	
26	370102610405	SPC-SCREW;M2.6L4,NIW,K-HD,t=0.8,NLK	22	PART	
27	370102010308	SPC-SCREW;M2L3,NIB,K-HD,HDt0.5,NLK	16	PART	
28	373102010601	T-SCREW;B,M2,L6,K-HD,NIB	4	PART	
29	340673400009	SCREW ASSY;CPU,8640S	3	ASSEMBLY	
30	422666200001	FFC ASSY;TOUCH PAD,CASE KIT,NV	1	PART	
31	371102011502	SCREW;M2L15,FLT(+),NIW/NLK	3	PART	
32	340671200020	FAN ASSY;8170	1	ASSEMBLY	

					/ /	TOL ±								DATE	05-Sep-02	MATERIAL	SEE NOTES	TREATMENT		REMARK	
					/ /		RANGE	M1	M2	S1	S2	P1	P2	C	B	UNIT	MM	SCALE	0.250	DRAWING NAME	CASE KIT;W/Z C/R,8640G
					/ /		0~6	.05	0.1	.15	0.2	.05	0.1	0.5	.15						
					/ /		6~30	0.1	0.2	.15	.25	0.1	.15	1	.15						
					/ /		30~80	.15	.25	0.2	0.3	0.2	0.4	2	.25						
					/ /		80~180	.15	0.3	.25	.45	0.4	0.8	3	.25						
					/ /		180~315	0.2	0.5	0.4	0.6	0.6	1.2	3	0.3						
					/ /		315~800	0.3	0.8	0.7	1.1	0.8	1.5	4	0.5						
ITEM	CONTENTS OF CHANGE				RVS	CHK	APV	M/D/Y													

MITAC International Corp.