



ITEM	PART NO	DESCRIPTION	Q'TY	TYPE	REMARK
1	340673440002	COVER ASSY;8640M	1	ASSEMBLY	
2	340673440001	HOUSING ASSY;8640M	1	ASSEMBLY	
3	340673420003	SHIELDING ASSY;TOP,8640P	1	ASSEMBLY	
4	411673440001	PWA;PWA-8640M,MOTHER BD	1	ASSEMBLY	
5	442673400009	BATT ASSY;14.8V/4AH,LI-MOLICEL,MSL,8640	1	ASSEMBLY	
6	523467343002	HDD ASSY;IC25N040ATCS04-0,IBM,8640D/M	1	ASSEMBLY	
7	523467343013	DVD COMBO ASSY;UJDA730,PANASONIC,8640D/M	1	ASSEMBLY	
8	340673420002	THERMAL ASSY;8640P	1	ASSEMBLY	
9	340673440005	COVER ASSY;KB,8640M	1	ASSEMBLY	
10	531020237566	KBD;88,UI,K010718Q1,8640,BLACK	1	PART	
11	340673400001	PLATE ASSY;K/B,8640S	1	ASSEMBLY	
12	344673440003	COVER;SPEAKER,8640M	1	PART	
13	340673400006	SPEAKER ASSY;BOX,8640S	1	ASSEMBLY	
14	442110500012	TOUCH PAD MODULE;TM41PUG311-2	1	PART	
15	340673420004	BRACKET ASSY;T/P,8640P	1	ASSEMBLY	
16	342673410001	BRACKET;CARD-READER,8640G	1	PART	
17	421673410003	FPC ASSY;CARD-READER,8640G	1	ASSEMBLY	
18	411673430004	PWA;PWA-8640D/M,ESB/LED BD	1	ASSEMBLY	
19	340673440004	COVER ASSY;MINI PCI,8640M	1	ASSEMBLY	
20	344673440026	COVER;R,HINGE,8640M	1	PART	
21	344673440008	COVER;L,HINGE,8640M	1	PART	
22	421673400003	MICROPHONE ASSY;8640S	1	ASSEMBLY	
23	377244010002	STANDOFF;#4-40DP3.5H5L5.5,NIW	4	PART	
24	370102610805	SPC-SCREW;M2.6L8,K-HD,NIW/NLK	15	PART	
25	370102010405	SPC-SCREW;M2L4,NIW,K-HD(+),NYLOK	21	PART	
26	370102610405	SPC-SCREW;M2.6L4,NIW,K-HD,+0.8,NLK	22	PART	
27	370102030301	SPC-SCREW;M2L3,K-HD,1,NIB/NLK	11	PART	
28	373102010601	T-SCREW;B,M2,L6,K-HD,NIB	4	PART	
29	340673400009	SCREW ASSY;CPU,8640S	3	ASSEMBLY	
30	422666200001	FFC ASSY;TOUCH PAD,CASE KIT,NV	1	PART	
31	371102011502	SCREW;M2L15,FLT(+),NIW/NLK	3	PART	
32	340671200020	FAN ASSY;8170	1	ASSEMBLY	
33	411673400014	PWA;PWA-8640P,T/P BD,T/U	1	ASSEMBLY	

					/ /	TOL ± RANGE								DATE	08-Nov-02	MATERIAL	SEE NOTES	TREATMENT		REMARK		
					/ /		MI	M2	S1	S2	P1	P2	C	B	UNIT	MM	SCALE	0.063	DRAWING NAME	CASE KIT;W/Z C/R,8640M		
					/ /	0~6	.05	0.1	.15	0.2	.05	0.1	0.5	.15	DRAWN	DESIGNED	CHECKED	APPROVED	MATERIAL NO.	AD	431673440001	
					/ /	6~30	0.1	0.2	.15	.25	0.1	.15	1	.15								
					/ /	30~80	.15	.25	0.2	0.3	0.2	0.4	2	.25								
					/ /	80~180	.15	0.3	.25	.45	0.4	0.8	3	.25								
					/ /	180~315	0.2	0.5	0.4	0.6	0.6	1.2	3	0.3								
ITEM	CONTENTS OF CHANGE	RVS	CHK	APV	M/D/Y	315~800	0.3	0.8	0.7	1.1	0.8	1.5	4	0.5	MITAC International Corp.							

**MITAC** *International Corp.*